目录

1. A fatal error occurred: Failed to connect to ESP32: Timed out waiting for packet header 2

AI机器人智造

1. A fatal error occurred: Failed to connect to ESP32: Timed out waiting for packet header



解决：

在界面上出现

Connecting……字样时候按住 boot 按钮即可，等到出现烧录的时候就可以松开了

AI机器人智造